

Anywhere Map Quadra Firmware Update 3-17-11

Release Notes for Anywhere Map v2.1 Build 608

1 | Page

- Runs in Portrait Mode or Landscape Mode.
- Consistent Interface Style throughout the system.
- Many contrast enhancing changes, improving view-ability in bright light conditions.
- Many user interface improvements.
- Fixed many minor cosmetic bugs with overlapping screen tags, or partially hidden items, etc... on the main map screen
- Fixed an issue that might occur if you were entering a value into an edit box, and clicked out of that edit box, causing a system error on an invalid value
- Updated the Sectional and UltraTAWS renderers to update more smoothly.
- Fixed the 'Play Click Sounds' setting on the System Menu - this now enables/disables the system-wide click sound handler.
- Made the option for Topo transparency larger, and easier to understand in the >Display Settings>Topo >Page 2 screen.
- Fixed the 'Hide Below Me'/'Red Above' Topo options for UltraTAWS.
- Fixed the Wind Vector display on the main map screen. The wind vectors were drawn incorrectly on the display, and thus the needle pointed at arbitrary directions, not the direction it was supposed to.
- Improved the Route Wizard logic. If an ambiguity between data entry points happens, the application now asks if you meant 'The Airport, Navaid... etc...'
- Fixed the Power Down routine to power the unit down when not in use, and on battery. This will not happen when moving, nor when plugged in.
- Added a tip in the Zoom Menu to show explain how to slide/zoom on the main map display screen.
- Fixed a draw issue dealing with Water. Baja Mexico exhibited this problem.
- Fixed an issue where the Auto Virtual ILS CDI may not disappear off-screen when it becomes disabled.
- Fixed the display of Blue/Blue METAR flags in the Airport Information screen.
- Added new High Visibility fonts/HSI. Also made the outlines of the CDI/Fonts larger for easier viewing.
- Fixed the Auto-zoom setting.
- Simplified the lookup of Airports, VORs, and Fixes.
- Added the Comments to the list of User Waypoints to make it easier to identify the waypoint you want to select.
- Fixed a bug that would cause the system to not operate if a corrupt settings file was loaded.
- Fixed and improved Emergency Mode.
- Replaced Slider style controls with a new + / - button system for easier entry of numbers. For an example, see the Sim Mode screen.
- Fixed a bug in the fuel price listings where you would sometimes get an (Unknown) type of fuel. It is now correctly labeled "JetA+" indication the fuel contains Prist.
- Fixed several WiFi related bugs.

